



0109

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S RT FE ROTATE BIO OIL

Make / Model	THWATES-ST	Date:	30/04/2026
Fleet Number	D109		
Hour Meter	2162 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 2200 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	N/A		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	N/A	
Tracks	N/A		Ad-blue level	N/A	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	✓		Electric		
Brakes as appropriate	✓		Cable Connections	✓	
Bodywork	✓		General Cleanliness	✓	
Operating Controls	✓		Battery Security	✓	
Warning Lights	✓				
Gauges/Instruments	✓		Other Checks		
Railings / boxing ring	N/A		Front left wheels		
Fan & other belts / chains	✓		Front right wheels		
Fuel cap secured	✓		Rear left wheels		
Lenses & mirrors	N/A		Rear right wheels		
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	N/A				

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AE Signature: [Signature]



H255

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X85-6	Date:	29/04/2026
Fleet Number	H255		
Hour Meter	5611 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 5805 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	✓	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	N/A	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	N/A	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AC Signature: [Signature]



H260

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S RT FE ROTATE BIO OIL

Make / Model	HX 85 - 6	Date:	29/04/2026
Fleet Number	H 260		
Hour Meter	1962 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 2144 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	✓	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	N/A	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	✓	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes
 ALL CHECKED OVER ALL GREASES AND CRANKED AROUND. ALL IN WORKING ORDER.

Engineers name: Ae Signature: [Signature]



H233

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x 735-6	Date:	28/04/2026
Fleet Number	# 233		
Hour Meter	5609 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 5685 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	✓				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes
 ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: KC Signature: [Signature]



H295

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x 225-7	Date:	28/04/2026
Fleet Number	H 295		
Hour Meter	756 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 1091 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓		Electric		
Operating Controls	✓		Cable Connections	✓	
Warning Lights	✓		General Cleanliness	✓	
Gauges/Instruments	✓		Battery Security	✓	
Railings / boxing ring	✓				
Fan & other belts / chains	✓		Other Checks		
Fuel cap secured	✓		Front left wheels		
Lenses & mirrors	✓		Front right wheels		
Rear & 360° cameras	✓		Rear left wheels		
Horn	✓		Rear right wheels		
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Defects / Service Details / Notes

ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name:

AC

Signature:

[Handwritten Signature]



H264

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X 26	Date:	28/04/2026
Fleet Number	H264		
Hour Meter	1515 hrs		

Machine Serviced	250 <input type="checkbox"/> 500 <input type="checkbox"/> 1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	---	---	--

Service due	1558 hrs
-------------	----------

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	✓	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	N/A	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	N/A	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	N/A	

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes **ALL CHECKED OVER ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER**

Engineers name: Ac.	Signature: [Signature]
----------------------------	-------------------------------



H230

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x48	Date:	28/04/2026
Fleet Number	H230		
Hour Meter	3640 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 4140 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	✓	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	N/A	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	N/A	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	N/A	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CURANED AROUND. ALL IN WORKING ORDER.

Engineers name: Ae Signature: [Signature]



H252

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X 26	Date:	27/04/2026
Fleet Number	#252		
Hour Meter	2235 247 hrs		

Machine Serviced	250 <input type="checkbox"/>	500 <input type="checkbox"/>	1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	------------------------------	------------------------------	-------------------------------	---	--

Service due	2672 hrs
-------------	----------

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	N/A	
Blade / stabilizers if fitted	✓		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	N/A				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	N/A				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER

Engineers name:	AE	Signature:	[Signature]
-----------------	----	------------	-------------



H253

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X 26	Date:	27/04/2026
Fleet Number	H253		
Hour Meter	1439 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 1939 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	N/A	
Blade / stabilizers if fitted	✓		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	N/A				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	N/A				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels	/	
Front right wheels		
Rear left wheels		
Rear right wheels		

X ORANGE ONE NOT WORKING

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED TROUBS. ALL IN WORKING ORDER

Engineers name: Ae Signature: N/Hybroney



H243

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x 225-7	Date:	27/04/2026
Fleet Number	H243		
Hour Meter	5033 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 5305 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	N/A	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	✓	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	
Refuelling Hose - present	✓	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AC

Signature: [Handwritten Signature]