



0109

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S  RT  FE  ROTATE  BIO OIL

Make / Model	THWATES-ST	Date:	30/04/2026
Fleet Number	D109		
Hour Meter	2162 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 2200 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	N/A		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	N/A	
Tracks	N/A		Ad-blue level	N/A	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓		<b>Electric</b>		
Steering if applicable	✓		Cable Connections	✓	
Brakes as appropriate	✓		General Cleanliness	✓	
Bodywork	✓		Battery Security	✓	
Operating Controls	✓		<b>Other Checks</b>		
Warning Lights	✓		Front left wheels		
Gauges/Instruments	✓		Front right wheels		
Railings / boxing ring	N/A		Rear left wheels		
Fan & other belts / chains	✓		Rear right wheels		
Fuel cap secured	✓				
Lenses & mirrors	N/A				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	N/A				

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AE Signature: [Signature]