



H255

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

|              |          |       |            |
|--------------|----------|-------|------------|
| Make / Model | 2X 85-6  | Date: | 29/04/2026 |
| Fleet Number | H255     |       |            |
| Hour Meter   | 5611 hrs |       |            |

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 5805 hrs

| Plant item                     | OK  | Defect | Fuel / Fluids             | OK   | Defect |
|--------------------------------|-----|--------|---------------------------|------|--------|
| Rams / bushings                | ✓   |        | Fuel Level                | 100% |        |
| Cab Guards/Covers              | N/A |        | Fuel connectors & pipes   | ✓    |        |
| Lifting eye / points           | ✓   |        | Engine Oil Level          | 100% |        |
| Cab glass                      | ✓   |        | Coolant Level             | 100% |        |
| Chassis bolts & security       | ✓   |        | Hydraulic fluid level     | 100% |        |
| Seat secure & fully adjustable | ✓   |        | Washer fluid level        | 100% |        |
| Tracks                         | ✓   |        | Ad-blue level             | N/A  |        |
| Blade / stabilizers if fitted  | ✓   |        | Refuelling Hose - present | N/A  |        |
| Seat & Seat Belt               | ✓   |        |                           |      |        |
| Steering if applicable         | N/A |        |                           |      |        |
| Brakes as appropriate          | N/A |        |                           |      |        |
| Bodywork                       | ✓   |        |                           |      |        |
| Operating Controls             | ✓   |        |                           |      |        |
| Warning Lights                 | ✓   |        |                           |      |        |
| Gauges/Instruments             | ✓   |        |                           |      |        |
| Railings / boxing ring         | N/A |        |                           |      |        |
| Fan & other belts / chains     | ✓   |        |                           |      |        |
| Fuel cap secured               | ✓   |        |                           |      |        |
| Lenses & mirrors               | ✓   |        |                           |      |        |
| Rear & 360° cameras            | ✓   |        |                           |      |        |
| Horn                           | ✓   |        |                           |      |        |
| Travel alarm                   | ✓   |        |                           |      |        |
| Lights / Beacons               | ✓   |        |                           |      |        |
| Obvious Leaks                  | N/A |        |                           |      |        |
| Safety pins & bolts            | ✓   |        |                           |      |        |
| Floor mats/ Air freshener      | ✓   |        |                           |      |        |

| Electric            | OK | Defect |
|---------------------|----|--------|
| Cable Connections   | ✓  |        |
| General Cleanliness | ✓  |        |
| Battery Security    | ✓  |        |

| Other Checks       | OK | Defect |
|--------------------|----|--------|
| Front left wheels  |    |        |
| Front right wheels |    |        |
| Rear left wheels   |    |        |
| Rear right wheels  |    |        |

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AC Signature: [Signature]