



H247

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

| | | | |
|--------------|---------|-------|------------|
| Make / Model | 2x135- | Date: | 08/05/2026 |
| Fleet Number | # | | |
| Hour Meter | 917 hrs | | |

| | | | | | |
|------------------|------------------------------|------------------------------|-------------------------------|---|--|
| Machine Serviced | 250 <input type="checkbox"/> | 500 <input type="checkbox"/> | 1000 <input type="checkbox"/> | Service Computer reset <input type="checkbox"/> | Service sticker updated <input type="checkbox"/> |
|------------------|------------------------------|------------------------------|-------------------------------|---|--|

| Service due | OK | Defect |
|--------------------------------|-----|--------|
| 1003 hrs | | |
| Rams / bushings | ✓ | |
| Cab Guards/Covers | N/A | |
| Lifting eye / points | ✓ | |
| Cab glass | ✓ | |
| Chassis bolts & security | ✓ | |
| Seat secure & fully adjustable | ✓ | |
| Tracks | ✓ | |
| Blade / stabilizers if fitted | N/A | |
| Seat & Seat Belt | ✓ | |
| Steering if applicable | N/A | |
| Brakes as appropriate | N/A | |
| Bodywork | ✓ | |
| Operating Controls | ✓ | |
| Warning Lights | ✓ | |
| Gauges/Instruments | ✓ | |
| Railings / boxing ring | ✓ | |
| Fan & other belts / chains | ✓ | |
| Fuel cap secured | ✓ | |
| Lenses & mirrors | ✓ | |
| Rear & 360° cameras | ✓ | |
| Horn | ✓ | |
| Travel alarm | ✓ | |
| Lights / Beacons | ✓ | |
| Obvious Leaks | N/A | |
| Safety pins & bolts | ✓ | |
| Floor mats/ Air freshener | ✓ | |

| Fuel / Fluids | OK | Defect |
|---------------------------|------|--------|
| Fuel Level | 100% | |
| Fuel connectors & pipes | ✓ | |
| Engine Oil Level | 100% | |
| Coolant Level | 100% | |
| Hydraulic fluid level | 100% | |
| Washer fluid level | 100% | |
| Ad-blue level | 100% | |
| Refuelling Hose - present | ✓ | |

| Electric | OK | Defect |
|---------------------|----|--------|
| Cable Connections | ✓ | |
| General Cleanliness | ✓ | |
| Battery Security | ✓ | |

| Other Checks | OK | Defect |
|--------------------|----|--------|
| Front left wheels | | |
| Front right wheels | | |
| Rear left wheels | | |
| Rear right wheels | | |

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: A.C.

Signature: [Signature]



R271

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

| | | | | | |
|------------------|------------------------------|------------------------------|-------------------------------|---|--|
| Make / Model | BOMAG ROWER | | Date: | 07/05/2026 | |
| Fleet Number | R271 | | | | |
| Hour Meter | 165 | hrs | | | |
| Machine Serviced | 250 <input type="checkbox"/> | 500 <input type="checkbox"/> | 1000 <input type="checkbox"/> | Service Computer reset <input type="checkbox"/> | Service sticker updated <input type="checkbox"/> |
| Service due | 500 | | hrs | | |

| Plant item | OK | Defect |
|--------------------------------|-----|--------|
| Rams / bushings | ✓ | |
| Cab Guards/Covers | N/A | |
| Lifting eye / points | N/A | |
| Cab glass | N/A | |
| Chassis bolts & security | ✓ | |
| Seat secure & fully adjustable | ✓ | |
| Tracks | N/A | |
| Blade / stabilizers if fitted | N/A | |
| Seat & Seat Belt | ✓ | |
| Steering if applicable | ✓ | |
| Brakes as appropriate | ✓ | |
| Bodywork | ✓ | |
| Operating Controls | ✓ | |
| Warning Lights | ✓ | |
| Gauges/Instruments | ✓ | |
| Railings / boxing ring | N/A | |
| Fan & other belts / chains | ✓ | |
| Fuel cap secured | ✓ | |
| Lenses & mirrors | N/A | |
| Rear & 360° cameras | N/A | |
| Horn | ✓ | |
| Travel alarm | ✓ | |
| Lights / Beacons | ✓ | |
| Obvious Leaks | N/A | |
| Safety pins & bolts | ✓ | |
| Floor mats/ Air freshener | N/A | |

| Fuel / Fluids | OK | Defect |
|---------------------------|------|--------|
| Fuel Level | 100% | |
| Fuel connectors & pipes | ✓ | |
| Engine Oil Level | 100% | |
| Coolant Level | 100% | |
| Hydraulic fluid level | 100% | |
| Washer fluid level | N/A | |
| Ad-blue level | N/A | |
| Refuelling Hose - present | N/A | |

| Electric | | |
|---------------------|---|--|
| Cable Connections | ✓ | |
| General Cleanliness | ✓ | |
| Battery Security | ✓ | |

| Other Checks | | |
|--------------------|--|--|
| Front left wheels | | |
| Front right wheels | | |
| Rear left wheels | | |
| Rear right wheels | | |

Defects / Service Details / Notes ALL CHECKED OVER. ALL IN WORKING ORDER.

Engineers name: AC Signature: [Signature]



H290

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

| | | | |
|--------------|---------|-------|------------|
| Make / Model | 2x 33 | Date: | 07/05/2026 |
| Fleet Number | H290 | | |
| Hour Meter | 374 hrs | | |

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 500 hrs

| Plant item | OK | Defect |
|--------------------------------|-----|--------|
| Rams / bushings | ✓ | |
| Cab Guards/Covers | N/A | |
| Lifting eye / points | ✓ | |
| Cab glass | ✓ | |
| Chassis bolts & security | ✓ | |
| Seat secure & fully adjustable | ✓ | |
| Tracks | ✓ | |
| Blade / stabilizers if fitted | ✓ | |
| Seat & Seat Belt | ✓ | |
| Steering if applicable | N/A | |
| Brakes as appropriate | N/A | |
| Bodywork | ✓ | |
| Operating Controls | ✓ | |
| Warning Lights | ✓ | |
| Gauges/Instruments | ✓ | |
| Railings / boxing ring | N/A | |
| Fan & other belts / chains | ✓ | |
| Fuel cap secured | ✓ | |
| Lenses & mirrors | ✓ | |
| Rear & 360° cameras | N/A | |
| Horn | ✓ | |
| Travel alarm | ✓ | |
| Lights / Beacons | ✓ | |
| Obvious Leaks | N/A | |
| Safety pins & bolts | ✓ | |
| Floor mats/ Air freshener | ✓ | |

| Fuel / Fluids | OK | Defect |
|---------------------------|------|--------|
| Fuel Level | 100% | |
| Fuel connectors & pipes | ✓ | |
| Engine Oil Level | 100% | |
| Coolant Level | 100% | |
| Hydraulic fluid level | 100% | |
| Washer fluid level | 100% | |
| Ad-blue level | N/A | |
| Refuelling Hose - present | N/A | |

| Electric | | |
|---------------------|---|--|
| Cable Connections | ✓ | |
| General Cleanliness | ✓ | |
| Battery Security | ✓ | |

| Other Checks | | |
|--------------------|--|--|
| Front left wheels | | |
| Front right wheels | | |
| Rear left wheels | | |
| Rear right wheels | | |

Defects / Service Details / Notes - ALL CHECKED, OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: AC

Signature: [Handwritten Signature]



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S RT FE ROTATE BIO OIL

| | | | |
|--------------|----------|-------|------------|
| Make / Model | 2X26- | Date: | 07/05/2026 |
| Fleet Number | H264 | | |
| Hour Meter | 1519 hrs | | |

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 1558 hrs

| Plant item | OK | Defect |
|--------------------------------|-----|--------|
| Rams / bushings | ✓ | |
| Cab Guards/Covers | N/A | |
| Lifting eye / points | ✓ | |
| Cab glass | ✓ | |
| Chassis bolts & security | ✓ | |
| Seat secure & fully adjustable | ✓ | |
| Tracks | ✓ | |
| Blade / stabilizers if fitted | ✓ | |
| Seat & Seat Belt | ✓ | |
| Steering if applicable | N/A | |
| Brakes as appropriate | N/A | |
| Bodywork | ✓ | |
| Operating Controls | ✓ | |
| Warning Lights | ✓ | |
| Gauges/Instruments | ✓ | |
| Railings / boxing ring | N/A | |
| Fan & other belts / chains | ✓ | |
| Fuel cap secured | ✓ | |
| Lenses & mirrors | ✓ | |
| Rear & 360° cameras | N/A | |
| Horn | ✓ | |
| Travel alarm | ✓ | |
| Lights / Beacons | ✓ | |
| Obvious Leaks | N/A | |
| Safety pins & bolts | ✓ | |
| Floor mats/ Air freshener | ✓ | |

| Fuel / Fluids | OK | Defect |
|---------------------------|------|--------|
| Fuel Level | 100% | |
| Fuel connectors & pipes | ✓ | |
| Engine Oil Level | 100% | |
| Coolant Level | 100% | |
| Hydraulic fluid level | 100% | |
| Washer fluid level | 100% | |
| Ad-blue level | N/A | |
| Refuelling Hose - present | N/A | |

| Electric | OK | Defect |
|---------------------|----|--------|
| Cable Connections | ✓ | |
| General Cleanliness | ✓ | |
| Battery Security | ✓ | |

| Other Checks | OK | Defect |
|--------------------|----|--------|
| Front left wheels | | |
| Front right wheels | | |
| Rear left wheels | | |
| Rear right wheels | | |

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED OVER. ALL IN WORKING ORDER.

Engineers name: AC Signature: [Signature]



H261

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

| | | | |
|--------------|----------|-------|------------|
| Make / Model | 2X 55-6 | Date: | 08/05/2026 |
| Fleet Number | H261 | | |
| Hour Meter | 2512 hrs | | |

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 2624 hrs

| Plant item | OK | Defect |
|--------------------------------|-----|-----------|
| Rams / bushings | ✓ | |
| Cab Guards/Covers | N/A | |
| Lifting eye / points | ✓ | |
| Cab glass | ✓ | |
| Chassis bolts & security | ✓ | |
| Seat secure & fully adjustable | ✓ | |
| Tracks | ✓ | VERY WORN |
| Blade / stabilizers if fitted | ✓ | |
| Seat & Seat Belt | ✓ | |
| Steering if applicable | N/A | |
| Brakes as appropriate | N/A | |
| Bodywork | ✓ | |
| Operating Controls | ✓ | |
| Warning Lights | ✓ | |
| Gauges/Instruments | ✓ | |
| Railings / boxing ring | N/A | |
| Fan & other belts / chains | ✓ | |
| Fuel cap secured | ✓ | |
| Lenses & mirrors | ✓ | |
| Rear & 360° cameras | N/A | |
| Horn | ✓ | |
| Travel alarm | ✓ | |
| Lights / Beacons | ✓ | |
| Obvious Leaks | N/A | |
| Safety pins & bolts | ✓ | |
| Floor mats/ Air freshener | ✓ | |

| Fuel / Fluids | OK | Defect |
|---------------------------|------|--------|
| Fuel Level | 100% | |
| Fuel connectors & pipes | ✓ | |
| Engine Oil Level | 100% | |
| Coolant Level | 100% | |
| Hydraulic fluid level | 100% | |
| Washer fluid level | 100% | |
| Ad-blue level | N/A | |
| Refuelling Hose - present | N/A | |

| Electric | | |
|---------------------|---|--|
| Cable Connections | ✓ | |
| General Cleanliness | ✓ | |
| Battery Security | ✓ | |

| Other Checks | | |
|--------------------|--|--|
| Front left wheels | | |
| Front right wheels | | |
| Rear left wheels | | |
| Rear right wheels | | |

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASES AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name: Ae Signature: [Signature]

