



H240

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X225-7		Date:	15/05/2026	
Fleet Number	H 240				
Hour Meter	5292 hrs				
Machine Serviced	250 <input type="checkbox"/>	500 <input type="checkbox"/>	1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
Service due	5388 hrs				
Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓		Electric		
Steering if applicable	N/A		Cable Connections	✓	
Brakes as appropriate	N/A		General Cleanliness	✓	
Bodywork	✓		Battery Security	✓	
Operating Controls	✓		Other Checks		
Warning Lights	✓		Front left wheels		
Gauges/Instruments	✓		Front right wheels		
Railings / boxing ring	✓		Rear left wheels		
Fan & other belts / chains	✓		Rear right wheels		
Fuel cap secured	✓		_____		
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓		Defects / Service Details / Notes		
Obvious Leaks	N/A		ALL CHECKED OVER. ALL GEARED AND CLEANED AROUND. ALL IN WORKING ORDER.		
Safety pins & bolts	✓		Engineers name: AC		
Floor mats/ Air freshener	✓		Signature: <i>[Signature]</i>		