



0118

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	THWATERL9T	Date:	21 / 04 / 2026
Fleet Number	P118		
Hour Meter	1169 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 1608 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	✓		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	N/A		Ad-blue level	N/A	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	✓				
Brakes as appropriate	✓				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	N/A				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels	✓	
Front right wheels	✓	
Rear left wheels	✓	
Rear right wheels	✓	

Defects / Service Details / Notes
 AND CHECKED ALL CHECKED OVER. ALL GREASES AND TROUBLE. ALL IN WORKING ORDER.

Engineers name: Ae. Signature: *[Signature]*