



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	21225-62	Date:	22.04.2026
Fleet Number	219		
Hour Meter	5843 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 6343 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	/		Fuel Level	100%	
Cab Guards/Covers	/		Fuel connectors & pipes	100%	
Lifting eye / points	/		Engine Oil Level	100%	
Cab glass	/		Coolant Level	100%	
Chassis bolts & security	/		Hydraulic fluid level	100%	
Seat secure & fully adjustable	/		Washer fluid level	100%	
Tracks	/		Ad-blue level	100%	
Blade / stabilizers if fitted	NA		Refuelling Hose - present	100%	
Seat & Seat Belt	/				
Steering if applicable	NA				
Brakes as appropriate	NA				
Bodywork	/				
Operating Controls	/				
Warning Lights	/				
Gauges/Instruments	/				
Railings / boxing ring	/				
Fan & other belts / chains	/				
Fuel cap secured	/				
Lenses & mirrors	/				
Rear & 360° cameras	/				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Electric	OK	Defect
Cable Connections	/	
General Cleanliness	/	
Battery Security	/	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes
 All checks done, cleaned all roads

Engineers name: Ae Signature: [Signature]